


Powerdot

935-PD11W-GST
 935-PD11-GST



CONTENT:

x1

x1

x1

A DRILL

Ø79

Drill a hole

B INSERT

Optional frame

C TURN CLOCKWISE & PLUG IN

Turn the plastic fastening nut as far up the thread as possible. Make sure that it has been thoroughly tightened. Lastly, connect the GST18i3.

55 mm maximum

1 CONNECT

Connect plug to Powerdot

2 RELEASE

Rotate counter clockwise

3 ADJUST

The inner part should now be loose. Adjust to desired level (see next step).

- 4 feed-throughs (Ø7, Ø9.5 mm)
 - 1 GST18i3
 Cable length according to order (max 1.2 m)

4 ADJUST LEVELS

LEVEL 1
0 mm / Flat

LEVEL 2
-6 mm / Sunk

LEVEL 3
-50 mm / Sunk

89 mm

95 mm

140 mm

5a LOCK Level 1 & 2
Rotate clockwise

5b LOCK Level 3
Rotate